

## ACTON St Mary

The bells are hung on plain bearings on one level in a fully braced oak frame installed c 1877. Bells one to seven inclusive have canons and the tenor has Doncaster type canons with a centre hole for independent type clapper staple - the remainder incorporate a cast in clapper staple

The bells may also be rung by Ellacombe hammers, the mechanism installed by John Warner and Sons when they cast and recast the bells. The Thwaites and Reed clock chimes the quarters on the 2<sup>nd</sup>, 3<sup>rd</sup>, 4<sup>th</sup> and 7<sup>th</sup> bells and the hours on the tenor. The clock is now electrically wound.

Peal boards