

## STANWELL. Sources

Tower: 1<sup>st</sup> stage C13 flint rubble... second stage flint and chequer C14, third stage smaller flint, late C14, spire shingled. Nikolaus Pevsner *Buildings of England: Middlesex* 1951. P. 149.

Rev E Huxtable of Stanwell ordered five leather mufflers 1901. WBF DB 199/97

31/12/1937 Order for new treble from Mr E G Sandels, builder. 27" 4-1-12. 46 letters of inscription. WBF DB 213/97.

Inscriptions on the bells:

Treble Mears & Stainbank London Lionel Wood of Brook Cottage Stanwell 1937.

Second T Mears & [sic] London Fecit 1825, John Telley, John Pott Churchwardens

Third C & G Mears, Founders London 1852 Joseph Bland Charles Batemans Churchwardens

Fourth T Mears of London Fecit 1813

Fifth Thomas Janaway of Chelsea Fecit 1786

Tenor R Well of Aldborne Fecit 1766. Ts Pott Ts Oander Ts Crew Churchwardens.

Weight of tenor 13-0-14.

From information sheet in tower.

The Chapter of St Paul's Cathedral offered a peal of eight for the five old Stanwell bells because of their superior quality. Charles Hoyal [incumbent] *Church guide*

Treble			Mears & Stainbank	1937
2 <sup>nd</sup>	29 ¾"	4-2-13	T Mears II	1825
3 <sup>rd</sup>	30 ¾"	5-1-6	C & G Mears	1852
4 <sup>th</sup>	33"	6-1-14	T Mears II	1813
5 <sup>th</sup>	36"	7-2-17	T Janaway	1786
Tenor	41 5/8"	13-0-14	R Wells	1766

G P Elphick *Draft schedule of bells in the Archdeaonry of Middlesex, Diocese of London.*

Box wooden frame on one tier

Treble 26 ¾" c. 4 ¼ cwt Mears & Stainbank 1937

*Schedule of bells.* Other details as in *Draft* as above.

All slips transcribed. PN 2021